

Appendix B Open Space Quality Deficiencies Highlighted in the Urban Renaissance Strategy (Sport, Recreation and Open Space Assessment, 2006)

Quality Deficiencies Highlighted in the Sport, Recreation and Open Space Assessment, 2006

Site Location	Site Name	Type
Outer King's Lynn	Riversway/Newlands Ave	Recreational grassland
	James Close	Recreational grassland
	Gaywood Park Allotment/link to community centre	Agricultural land in built up area/footpath
	Lawrence Road	Former bowling green - now community centre
	Danton Close Playing Fields	Playing fields
Inner King's Lynn	St Johns Walk	Outdoor sports facilities
	Boal Quay	Recreational grassland and unused land
	Winfarthing Avenue	Recreational grassland/amenity greenspace
	All Saints Church	Church and surrounding cemetery
	Kettlewell Lane	Wildlife area
	Hextable Lane	Recreation ground
	North End	Recreation ground
West Lynn	Kempe Road	Recreational grassland
Downham Market	Snape Lane	Recreational grassland/amenity greenspace/children's playground
Stowbridge	Play equipment is poor quality	Stowbridge
Lakesend	Churchyard poor quality	Lakesend
Tottenham Row	Common inadequately maintained	Tottenham Row
West Acre	Sport pitches at River Road poorly maintained	West Acre
Barroway Drove	Sport pitches poorly maintained	Barroway Drove
Castle Acre	Playing fields have drainage problems which restrict pitch use	Castle Acre



Site Location	Site Name	Type
Methwold	Pitch and pavilion at recreation ground requires upgrading	Methwold

Source: Sport, Recreation and Open Space Assessment, 2006

