

Hunstanton Void Inspection Video 1 – (AM Visit)

Monday 23rd February 2026

Borough Council of
**King's Lynn &
West Norfolk**







Void filled in 2023

Water in base of hole at High Tide

Asphalt Prom

Section F



Section F

Looking north towards Rock Shop



Void filled in 2023

Looking east towards Car Park



Looking south towards Oasis



Section E





Void filled in 2023

Looking east towards Car Park

Looking south towards Oasis



Section F Prom



Looking north towards Waterside Bar



Looking east towards Car Park



Hunstanton Void Inspection Video 2 – (PM Visit)

Monday 23rd February 2026

Borough Council of
**King's Lynn &
West Norfolk**



Void filled in 2023

Looking south towards Oasis

Section E Seawall

Base of wall





Void filled in 2023

Looking south towards Oasis

1920's prom slab

Section E Seawall

Base of wall





Void filled in 2023

Looking south towards Oasis

Section E Seawall

Base of wall



Fill beneath Section F

Section F asphalt



Looking east towards car park

Section F Asphalt Prom

Void filled in 2023


Section F asphalt

Looking east towards car park

Borough Council of
King's Lynn &
West Norfolk



Section F Asphalt Prom



Section F asphalt

Looking towards Waterside Bar

Hunstanton Void Inspection Video 3 – (PM Visit)

Monday 23rd February 2026

Borough Council of
**King's Lynn &
West Norfolk**




Void filled in 2023

Looking south towards Oasis

Section E Seawall





Void filled in 2023

Looking south towards Oasis

Section E Seawall

Base of wall





Void filled in 2023

Section F Seawall

Section E Seawall

Base of wall





Section F Asphalt Prom

Section F Seawall

Looking north towards Rock Shop



Section F Asphalt Prom

Section F Seawall

Looking north towards Rock Shop

Section F Asphalt Prom

Looking east towards Car Park

Section F Asphalt Prom

